

Unismart Product Update Notification

December 2nd, 2016

HP OEM Resetting Detection Function Added

1. We added detection function before resetting HP OEM chips so as to avoid a repeated reset that wastes credit.

2. Unismart device:

Item	Before	After
Firmware version	≤V3.25.1	V3.25.2
Bootload version	≤V3.8C	V3.9C

- ◆ Customers can upgrade the Unismart according to their needs.
- ◆ The upgrade is only for HP OEM reset, the other products will not be affected.

After upgrade, the related firmware version is V3.25.2. To upgrade the Unismart, please log in ApexClient.

For more information, please contact your sales manager.

Note: please tick the product list and system when update package.

"Apex" herein refers to Apex Microelectronics Co., Ltd. The information contained herein is subject to change without prior notification. Apex shall not be liable for technical or editorial errors or omissions contained herein. Photographed products may not always match the description.