Unismart Product Update Notification

Date: **December, 2017**

Recently, Apex found that Samsung MLT-D111 series cartridges installed with new replacement chips cannot be recognized by the printer SL-M2077F (firmware version: 3.00.01.30，SEP-27-2016; applicable region: DOM) produced in July 2017. Currently, Apex has upgraded this series of products and Unismart system.

1. Unismart Device

Subject	Before	After
Firmware Version	≤V3.25.6	V3.25.7

2. Uni-JIG Update

JIG Code	Item	Before	After	Reason of Change
ST1	Software Version	≤V3.1	V3.2	To resist firmware upgrade

If there is any question, please contact your sales manager.